Foam Cutter Tutorial

Digital Media Lab Equipment Tutorial 2003 - 2004

The foam cutter cuts by a moving heated wire. It can cut a maximum volume of 96" x 96" x 48". The foam cutter can cut white expanded polystyrene foam, blue ridged foam, and pink ridged foam.

- Note: All 3D objects cut on the foam cutter are derived from 2D shapes. This will require you to calculate the 3D object into 2D shapes.
 - All 2D shapes to be cut on the foam cutter need to be exported as a .dxf file.

- 2D shapes can be created in any 2D or 3D modeling or drafting application such as AutoCAD, Rhino, Maya, Form Z, Vectorworks, Illustrator.

Step 1: Create your 2D profiles:

2D shapes drawn in a 3D modeling program.



Step 2: Export the 2D shapes as a .dxf file:

1 - Select File - Export Selected.

¥

		Release 14 of earlier.	_
Untitled -	Rhinoceros (Edu	AutoCAD Export Options	Þ
e Edit View	v Curve Surface	AutoCAD version	
New	Ctrl+N	C Release 12	
Open	Ctrl+O	C Release 13 (● Release 14	
Save	Ctrl+S	C 2000	
Save Small			
Incremental S	Save	Save curves as	
Save As Save As Tem	plate	C Polylines	
		Save surfaces as	
Insert	Ctrl+I	Polyagon meshes	
Import		C Curves	
Export Select	ed	Save polygon meshes as	
Export With C	Drigin	Polyface mether	
Notes		C 3D Faces	
Properties		Curve options	
Duinh	Chillip	Project to plane	
Princ	Cm+P	✓ Use simple entities	
Print Preview		Simplify tolerance:	0.05
Print Setup		Poluline max angle:	10
Worksession I	Manager	Poluline chord bejaht	100000
Send		Debuter and the second s	0
Exit		Polyline seg length:	10
		OK Cancel	Help

2 - If the application gives you an export option, save the .dxf file as **Release 14** or earlier.

Step 3: Import .dxf file into Croma Designer:

	• • • •		a	. .
1	- Set the	e Import	Options	first.

🚟 CROMA DESIGNER					
File Edit	Options	View	Help		
✓ Information			Home		
	Impor	Import Options			
Points	7				
0.000	1				
0.000	i I				
0.000					

2 - If you have multiple shapes that need to be linked together, select **Objects with links**.

If you have a continuous line without breaks, select **Polyline**.

Default import options	×
Drawing © Objects with links © Polyline	Cancel
Links © No automatic linking © Automatically link on import	

3 - Select File - Import - DXF.

🛣 CROMA DESIGNER				
File Edit Option	ns View	Help		
Open Save Designer Save Cut Mana Save Output fil	file F agerfile le	2	Link	
Import		•	HPGL	
Quit			DXF	
2				

Step 4: Adjust file settings in Croma Designer:



rework the links between the shapes.



Hit enter at his prompt.

Step 5: Save the Croma Designer files:

ROMA E:\TEMP\FOAM		Save As		? ×
File Edit Options View Help Open Save Designer file F2 Save Cut Manager file Save Output file Import Import Quit	Save the file as a Project .PRJ file.	File name: FOAMCU ^{~1} .PRJ	Folders: e:\temp e:\ E e:\ E Temp	OK Cancel Network
		, Save file as type:	Drives:	

Projet (*.PRJ)

-

e: Scratch

Step 6: Cut the profiles with Croma Output:



Step 7: Connect to the Foam Cutter:

1 - Position your foam on the Foam Cutter platform. The foam should be standing on its own, and the platform should be clear of any other objects.

2 - Turn on the Foam Cutter.

3 - Connect the Croma Output software to the Foam Cutter by selecting System - Connect. If connection is successful, you'll see a green dot with the words "Machine connection."

Control	- 🗆 ×
Help System	
Machine	connection
	V inch X 0.11 Y 0.16 RST
	deg 179.0 RST
	inch U 0.11 V 0.16 RST
STOP 0%]0
Points	Wire

-



The control panel is used to manually move the wire. Before proceeding with your cut, you should make certain that the wire is square and level.

Step 8: Level the Foam Cutter Wire:

Make sure the **XY** = **UV** checkbox is checked. This makes the left and right sides of the wire are moving in tandem. Leaving this unchecked could break the wire.

Use the left and down arrows in the **XY** pane to move the wire as far to the left and bottom as it will go. You will see a red dot appear next to the arrows when the wire has reached its limit.

NOTE: you can click the **F** button to move the wire faster, but only when not cutting. Moving the wire fast though foam when cutting can break the wire.

When the wire has been moved to the bottom left, you should see red dots next to the left and down arrows in both the XY and UV panes. If you do not see a red dot, that means the wire is not at its limit. If this is the case, uncheck XY = UV, click S, and click the arrow that does not have a red dot until the dot appears.

For example, In the image to the left, we would click the UV down arrow until the dot appears to level the wire.

Once you see red dots next to both sets of left and down arrows, the foam cutter wire has been squared and leveled, and you're ready to proceed with your cut. Check the **XY** = **UV** checkbox and continue.

Step 9: Cutting with the Foam Cutter:

1 - Make sure the plastic doors of the Foam Cutter are closed.

2 - Using the control panel, position the wire to the starting point of the cut (indicated in Croma Output by the small circle).

3 - Click on Cut to start cutting your file.

