

VENDOR W/O # 150298-01

Service Date 3/29/22 03:15 PM to 3/29/22 03:15 PM

Priority Regular Order Type Service SN Task # PRJTASK10129748

Telaid 13 West Main Street Niantic, CT 06357

Contact Information Service Desk (866) 566-4295

SERVICE LOCATION UBS - Loc # FL50 - FLORHAM PARK, NJ 500 CAMPUS DRIVE null FLORHAM PARK, NJ 07932 Phone # Fax #

VENDOR # 380129 Intellicomm 1048 Chase Creek Ct Lawrenceville, GA 30044 Phone # 405-802-1262 Fax #

_____ SERVICE DESCRIPTION Equipment Migration *FIRM ETA* ETA Requirements: 3/29/22 3:15 PM EST Day or Night work: Day Estimated Time on Site: 1-4 Hrs How many techs? 1 How many planned trips: 1 LCON: Scope of Work: Turn up circuit for new equipment, tech must have a Fiber patch cord - LC/LC Connectors Single Mode Fiber 30ft handy for the migration. Tech must check in and out with Telaid while onsite, failure to do so may delay payment. Need help from TelAid to assist in circuit migration, moving UBS equipment over to a new circuit. Tech must arrive onsite on time, cannot be late. Please be onsite and ready to work at the requested ETA. If traffic is suspected to be an issue, please leave a bit earlier to ensure arrival to site on time. Tech will be working with Julia, UBS tech, and the service provider to do the cutover during a 1-hour long call. Techs must be familiar with Verizon, ATT, and Juniper circuits and cutovers. **Tech should have a understanding about SFPs/GBic as they may be required to deal with while onsite. Modules are delicate and require gentle handling and ideally should not be done with tech who never handled them for this case. Attached picture in documents shows what would ideally be onsite, is not exactly what is onsite but should have a similar set up. Tech must also take pictures of the site so Michael can confirm the circuits are the right ones we are going to. Tech must arrive onsite ready to work at the appointed ETA. Missing said ETA will cause site to be rescheduled, rescheduling process takes about 2 weeks to confirm. Customer PO: _____ Doc Type Required Count Description 1 Signed Work Order must include check in/out times and description of

work



Telaid 13 West Main Street Niantic, CT 06357 SIGN OFF SHEET VENDOR W/O # 150298-01

Service Date 3/29/22 03:15 PM to 3/29/22 03:15 PM

Priority Regular Order Type Service SN Task # PRJTASK10129748

SERVICE LOCATION UBS - Loc # FL50 - FLORHAM PARK, N. 500 CAMPUS DRIVE null FLORHAM PARK, NJ 07932 Phone # Fax #	J	IVR Pin # 63818459
Equipment Migration *FIRM ETA* ETA Requirements: 3/29/22 3:15 PM EST Day or Night work: Day Estimated Time on Site: 1-4 Hrs How many techs? 1 How many planned trips: 1 LCON: Scope of Work: Turn up circuit for new equipment, tech must have a Fiber patch cord - LC/LC Connectors Single Mode Fiber 30ft handy for the migration. Tech must check in and out with Telaid while onsite, failure to do so may delay payment. Need help from TelAid to assist in circuit migration, moving UBS equipment over to a new circuit. Tech must arrive onsite on time, cannot be late. Please be onsite and ready to work at the requested ETA. If traffic is suspected to be an issue, please leave a bit earlier to ensure arrival to site on time. Tech will be working with Julia, UBS tech, and the service provider to do the cutover during a 1-hour long call. Techs must be familiar with Verizon, ATT, and Juniper circuits and cutovers. **Tech should have a understanding about SFPs/GBic as they may be required to deal with while onsite. Modules are delicate and require gentle handling and ideally should not be done with tech who never handled them for this case. Attached picture in documents shows what would ideally be onsite, is not exactly what is onsite but should have a similar set up. Tech must also take pictures of the site so Michael can confirm the circuits are the right ones we are going to. Tech must arrive onsite ready to work at the appointed ETA. Missing said ETA will cause site to be rescheduled, rescheduling process takes about 2 weeks to confirm. Customer.PO:		
Store Manager's Signature		-
Print Name	Date	-
Time In	Time Out	-
Print Date: 03/26/22 team@intellico	mmservices.com	Page 1 of 1