

**Network Engineering Technologies** 3140 Deming Way Middleton, WI 53562 www.nettechnology.com

Vendor: 60426

Purchase Order: 649283-1311477-07772

Work Order: 1311477

Service ETA: 8/18/2021 2:00 PM

\*Purchase Order MUST appear on all invoices and emailed to apinbox@nettechnology.com or invoice will be rejected, Invoice must match this Purchase Order Receipt.

**Site Location Information** 

**Customer:** CVS Pharmacy

Site Number: 07772 **Location:** pharmacy 10710 State Bridge Rd Alpharetta, GA 30022

() -

**Site Contact:** 

**Technician Information** 

Technician Name: Thishawn Bessor **Technician Phone:** (347) 777-2900

**Techs Manager:** Vendor Manager

**Manager Phone:** 4058021262

# \*\*\* MUST CALL UPON ARRIVAL AND BEFORE SITE DEPARTURE \*\*\*

Info:

Please Call: 1 608 827-2270 \*Your call will be handled in the order received\* The **Contact** following Login information is needed: your name, Company Name, work order#,

callback number(mobile#)

## Scheduling

1 billable technician required Arrival Time: 8/18/2021 2:00 PM

### Scope of Work

## CVS Register 2021 Project

NET techs will LOG IN/LOG OUT LIVE by calling (608) 827-2270. Do not auto log in.

CALL CVS ROC 888-401-4601, Option 6 \*\*In order to ensure accurate onsite times, tech will need to log in with NET Support and then immediately log in with CVS ROC. At log out, ROC will provide you a log out code.

If the store personnel question the validity of this visit, the manager can call 866-528-7272, Option 1.4 (CVS Helpdesk) or can reference this CVS Help Desk ticket number: June & July INC10272631

#### PPE requirement: Use of Face Masks or Cloth Face Covers

SOW: Tech will replace Registers as described in the Redbook. Existing 742 model registers may be located in the Pharmacy or Front Store. Tech will need to work with CVS ROC to identify specific units that will require replacement. Note it will be important that tech records old serial numbers of each register replaced on Appendix provided. Techs will need to replace some Register Memories too base on what was sent to site and per the completed survey. Please confirm the actual Register Number with CVS ROC where these will need to be replaced. Tech will need to replace some Receipt Printers too based on what was sent to site. Please confirm the actual Register Number with CVS ROC where these will need to be replaced.

Required Scope of Work:

Device Register Replacement Register Memory Upgrade 0 Affected Register # Register Receipt Printer 0 Affected Register # 0

#### Materials:

- -cable tester
- -cable toner
- -label marker
- -basic hand tools



Network Engineering Technologies 3140 Deming Way Middleton, WI 53562 www.nettechnology.com Vendor: 60426

Purchase Order: 649283-1311477-07772

Work Order: 1311477

Service ETA: 8/18/2021 2:00 PM

\*Purchase Order MUST appear on all invoices and emailed to apinbox@nettechnology.com or invoice will be rejected, Invoice must match this Purchase Order Receipt.

Req	uired	<b>Pictures:</b>
-----	-------	------------------

- 1. Each register unit replaced
- 2. Overview photo of area
- 3. Return shipping label
- 4. Appendix A
- 5. Appendix C
- 6. Appendix D

~_II		£					
all	$ V  \vdash  V $	TOT	anv	ULIECTIONS	$\alpha$ r	CONCARNO	ONCITA
-an		101	uliv	questions	OI.	COLICCIA	Ulisite

Pictures must be emailed to dss@nettechnology.com, before tech is released from site. When sending pictures the email subject line must read "[xxxxxx]" where xxxxxx= WO ID found on Purchase Order; usually 6 digits long. \*\*\*IMPORTANT — Subject line must be enclosed in BRACKETS [ ] and not PARENTHESIS ( ).\*\*

Resolution							
_							
	rts List. Total Parts: 4						
PartName	Used	QTY					
CVS Register Install	Yes	1					
Trip Charge	Yes	1					
CVS Register Memory	Yes	0					
POS_Printer	Yes	0					
Customer - Managers Name (PRINT)	Customer - Managers Name (SIGN)	Date Time					
Technicians Name (PRINT)	Technicians Name (SIGN)	Date Time					
MANDATORY SIGN OFF OF TE	CHNICIAN AND CUSTOMER CONTAC	CT MANAGER					

Sign Off does not release tech from the job site. Any questions need to be directed to NET Tech Support.