Chartered Surveyors Commercial Property Consultants Valuers





CHURCH HALL PREMISES

183 m² (1,959 ft²)

Tarleton Methodist Church Hall 194 Hesketh Lane Tarleton PR4 6AT

- Centrally located to the Village
- Ideal for a range of uses (s.t.p.)
- Flexible terms available
- Car parking and main road access

www.eckersleyproperty.co.uk

Preston officeT |25A Winckley SquareE |PrestonPR1 3JJ

T | 01772 883388 E | preston@eckersleyproperty.co.uk Lancaster office T | 01524 60524 Castle Chambers E | lancaster@eckersleyproperty.co.uk China Street Lancaster LA1 1EX







Location

Prominently situated slightly to the side and rear of the main Methodist Church just to the north of Tarleton Village.

Hesketh Lane is the main road linking Tarleton to Hesketh Bank. The property is located close to a number of local amenities.

Description

Single-storey building constructed in an Lshape configuration. There is a single-storey annex to the rear of the main hall which faces the private road which runs adjacent to the main chapel.

Internally, the accommodation comprises a hall with ancillary areas to include a fitted kitchen, private office, store rooms, separate male and female WC facilities and a disabled WC.

Externally, there is potential for car parking for up to 7/8 vehicles.

Accommodation

The premises extend to the following net internal area:

Main Hall	m² 116	ft ² 1,250
Meeting Room	29	308
Office	6	60
Kitchen	9	97
Storage	23	244
Total	183	1,959

Services

All mains services are either available or connected to the property.

Rating Assessment

Not yet assessed for rating purposes.

Interested parties are recommended to make their own separate enquiries with the Rating Department of West Lancs District Council (tel. 01695 587158).

Planning

The property benefits from a use classification of D1 (non-residential institution) under the Town & Country Planning (Use Classes) Order 1987 (as amended).

Interested parties should make their own separate enquiries of the Local Planning Authority – West Lancs District Council (tel. 01695 577177).

Terms

The premises are available by way of a new lease on terms to be agreed.

Rental

Offers in the region of £13,000 per annum, exclusive.


Photographs and Plans

Any photographs and indicative plans incorporated in these particulars are provided for identification purposes only and should not be relied upon.

Energy Performance Certificate

Energy Performance Certificate Non-Domestic Building	HMGovernment
COMMUNITY HALL Tarleton Methodist Church Church Road Tarleton PRESTON PRESTON PRE SUP	Certificate Reference Number 9624-3047-0119-0901-032
This certificate shows the energy rating of this building the building fabric and the heating, ventilation, cooling compared to two benchmarks for this type of building: one appropriate for existing buildings. There is more adv in the aviidneed document. Energy Bedramana Cadifi	g and lighting systems. The rating is one appropriate for new buildings and rice on how to interpret this information

In the guidance document *Energy Performance Certificates for the construction, sale and let of non-divellings available on the Government weekle at www.gov.uk/government/collections/energy-performance-acettificates.
Energy Performance Assol Rating
Mose sentry efficient*



Legal Costs

Each party to be responsible for their own legal costs incurred in this transaction.

Enquiries

Strictly by appointment with the sole agents:		
Eckersley		
Telephone:	01772 883388	
Contact:	Fiona Warren / Harry Holden	
Email:	fw@eckersleyproperty.co.uk/	
	hjh@eckersleyproperty.co.uk	

Eckersley for themselves and for the vendors or the lessors of this property whose agents they are give notice that i). The particulars are set out as a general outline only for the guidance of the intended purchaser or lessees and do not constitute any part of an offer or contract. ii) All descriptions, dimensions, references to condition and necessary permissions for the use and occupation, and other details are given in good faith but without responsibility and intended purchasers or tenants should not rely on them as statements or

