


WOOD DESTROYING PESTS AND ORGANISMS INSPECTION REPORT

Building No. 12345	Street Main St.	City Anytown CA.	Zip 98765	Date of Inspection 05/09/2011	Number of Pages Page 1 of 12
		On-Site Inspections, Inc. 461 Alta Vista Dr. South San Francisco, Ca. 94080 650-520-8953 650-952-5173		A LICENSED PEST CONTROL OPERATOR IS AN EXPERT IN HIS/HER FIELD. ANY QUESTIONS RELATIVE TO THIS REPORT SHOULD BE REFERRED TO HIM/HER.	
PROPERTY & TERMITE INSPECTION SERVICES		Registration # PR-5244	Report # 0005807		
Ordered by Joe and Jane Doe 481 Main St. Anytown, CA	Property Owner and/or Party of Interest Joe and Jane Doe 481 Main St. Anytown, CA	Reported by Joe and Jane Doe 481 Main St. Anytown, CA 98765			
COMPLETE REPORT <input checked="" type="checkbox"/> LIMITED REPORT <input type="checkbox"/> SUPPLEMENTAL REPORT <input type="checkbox"/> REINSPECTION REPORT <input type="checkbox"/>		General Description Two Story, Single Family Residence.			
		Inspection Tag Posted Garage		Other Tags Posted None Noted	
An inspection has been made of the structure shown inside, together with, in accordance with the Structural Pest Control Act, detached porches, detached sheds, detached decks and any other structures. Noted: No termites or other wood destroying organisms were inspected.					
Subterranean Termites <input checked="" type="checkbox"/> Drywood Termites <input type="checkbox"/> Fungus/Dryrot <input checked="" type="checkbox"/> Other Findings <input type="checkbox"/> Further Inspection <input checked="" type="checkbox"/>					
(If any of the above boxes are checked, it indicates that a wood-damage problem is possible exists. Read the report for details on checked items.)					
Key: 1 = Substructure 2 = Stair/Slipper 3 = Foundation 4 = Porches/Steps 5 = Ventilation 6 = Abutments 7 = Attic 8 = Garage 9 = Deck/Patio 10 = Interior 11 = Exterior					



Note: Diagram Not to Scale

Inspected By: Mark Steven Rush State License No. OPR-10085 Signature *Mark Steven Rush*

You are advised to obtain copies of all reports and completion notices on file presently reported to the Structural Pest Control Board during the preceding two years. To obtain copies contact: Structural Pest Control Board, 2225 Foothill Blvd., Suite 1508, Sacramento, California 95815.
 NOTE: Questions or problems concerning the above report should be directed to the manager of the company. Unresolved questions or problems with services performed may be directed to the Structural Pest Control Board at (916) 551-8709, (800) 737-0260 or www.spccb.org. 434-41 (PRC) (1801)