



By accepting this work order and performing the mentioned above services you are accepting the terms and conditions set forth in the Master Contractors Agreement.

CUSTOMER INFORMATION:

Customer: Advance Auto Parts

Site: Advance Auto Parts #5283 - Washington Ro

Address: 4018 Washington Rd

Martinez, GA 30907

Corner Address:

Phone: 706-868-5157

Requested By: 65616

Problem Code: 100 Misc Multi-Site Project

CROSSCOM NATIONAL INFORMATION:

Contact: Jennifer Chovan

Log in and out via IVR: (800) 820-9229

Fax D&A to: (800) 933-5538

Questions? Call: (800) 820-9229

BRIEF STATEMENT OF WORK & COMMENTS

AAP - Battery/Alternator Tester MAC - 42083

TRIP INFORMATION

Arrival Date	Arrival Time	Time Zone	Trip Description	# Of Techs
10/06/2020	08:00 AM	EDT	MAC Go Back	1

TECHNICAL NOTES:

The technician must troubleshoot the battery/alternator cable run that is offline with Eve Bird 540-561-1239 @AAP between the hours of 8am - 4pm EST Monday - Friday.

* Trips: 1 technician will be required and the work will be done during business hours.

* Special tools: Laptop w/aircard, cell phone for pictures, label maker, Cat 6 cable tester with downloadable results, ladders (6', 10' & 12'), 9/16 wrench or ratchet w/9/16 socket (for removing rack from pallet). standard data hand tools.

* Technicians will log in and out with CrossCom Project Team @ 800-820-9229.

* Deliverables will be required to validate work completion and craftsmanship. All deliverables must be uploaded through the vendor portal prior to leaving the work site. Failure to provide deliverables will result in non-payment.

MATERIAL ON ORDER

Part Number	Part Description	Provided By	Quantity
None			

SPECIAL TOOLS

Description	Provided By
Laptop with AirCard	VFT
Digital Camera	VFT
Label Maker	VFT
Cat6 Cable Tester w/ Downloadable Reults	VFT
Ladders (6', 10' & 12')	VFT
9/16" wrench or ratchet w/ 9/16" socket	VFT
Standard Data Hand Tools	VFT

OPTIONAL ITEMS (Confirm with CrossCom before performing any of these activities.)

Description
None

DELIVERABLES

Required before last trip checkout.



Description	Acceptance Criteria	Type
Delivery & Acceptance		Delivery & Acceptance
Cable Test Results	Downloadable Test Results or Photo showing jack and store number in the photo with passing results	Cable Certification
Work completed - Photo Slot 1	Overall view, 3-5' away (with store number sign)	Pictures
Work completed - Photo Slot 2	Overall view, 3-5' away (with store number sign)	Pictures



DELIVERY & ACCEPTANCE (D & A):

Trip # _____ Date _____ On-Site At _____ Off-Site At _____

Manager Signature _____ Manager Printed Name _____

Additional Trip Required? Yes / No

Description of Work: _____

Customer Abuse: Yes / No Explain: _____

Trip # _____ Date _____ On-Site At _____ Off-Site At _____

Manager Signature _____ Manager Printed Name _____

Additional Trip Required? Yes / No

Description of Work: _____

Customer Abuse: Yes / No Explain: _____

CHECKLIST

1. What was the length of the cable run? _____
2. Where were you instructed to run the cable for the placement of the Alt/Battery tester? _____
3. Name of the Manager on duty that gave the instruction. _____
4. Any additional materials used that were not supplied? _____
5. Date and time you worked with Eve @AAP _____
6. Checkout or INC # provided by Eve _____
7. What was the issue with battery/alternator tester _____
8. What delays did you have if any? Please provide times and delay descriptions: Example: 30 mins due to hold times, 1 hr looking for materials _____



COMMENTS & SIGNATURES

Comments _____

Manager Signature _____ Date & Time _____

Technician Signature _____ Date & Time _____