

By accepting this work order and performing the mentioned above services you are accepting the terms and conditions set forth in the Master Contractors Agreement.

CUSTOMER INFORMATION:

Customer: Advance Auto Parts

Site: Advance Auto Parts #6127 - Wrightsboro R

Address: 5140 Wrightsboro Rd

Grovetown, GA 30813

Corner Address:

Phone: 706-228-4455

Requested By: 65616

Problem Code: 100 Misc Multi-Site Project

CROSSCOM NATIONAL INFORMATION:

Contact: Jennifer Chovan Log in and out via IVR: (800) 820-9229

Fax D&A to: (800) 933-5538 Questions? Call: (800) 820-9229

BRIEF STATEMENT OF WORK & COMMENTS

AAP - Battery/Alternator Tester MAC - 42083

TRIP INFORMATION

Arrival Date	Arrival Time	Time Zone	Trip Description	# Of Techs
10/06/2020	08:00 AM	EDT	MAC Go Back	1

TECHNICAL NOTES:

The technician must troubleshoot the battery/alternator cable run that is offline with Eve Bird 540-561-1239 @AAP between the hours of 8am - 4pm EST Monday - Friday.

- * Trips: 1 technician will be required and the work will be done during business hours.
- * Special tools: Laptop w/aircard, cell phone for pictures, label maker, Cat 6 cable tester with downloadable results, ladders (6', 10' & 12'), 9/16 wrench or ratchet w/9/16 socket (for removing rack from pallet). standard data hand tools.
- $\mbox{\ensuremath{^{*}}}$ Technicians will log in and out with CrossCom Project Team @ 800-820-9229.
- * Deliverables will be required to validate work completion and craftsmanship. All deliverables must be uploaded through the vendor portal prior to leaving the work site. Failure to provide deliverables will result in non-payment.

MATERIAL ON ORDER

Part Number	Part Description	Provided By	Quantity
None			

SPECIAL TOOLS

Description	Provided By
Laptop with AirCard	VFT
Digital Camera	VFT
Label Maker	VFT
Cat6 Cable Tester w/ Downloadable Reults	VFT
Ladders (6', 10' & 12')	VFT
9/16" wrench or ratchet w/ 9/16" socket	VFT
Standard Data Hand Tools	VFT

OPTIONAL ITEMS (Confirm with CrossCom before performing any of these activities.)

Description

None

DELIVERABLES

Required before last trip checkout.

Description	Acceptance Criteria	Type
Description	Acceptance criteria	Type



Delivery & Acceptance		Delivery & Acceptance
Cable Test Results	Downloadable Test Results or Photo showing jack and store number in the photo with passing results	Cable Certification
Work completed - Photo Slot 1	Overall view, 3-5' away (with store number sign)	Pictures
Work completed - Photo Slot 2	Overall view, 3-5' away (with store number sign)	Pictures



DELIVERY &	ACCEPTANCE (D & A)	<u> </u>		
Trip #	Date	On-Site At	Off-Site At	
Manager Signat	ture	Manager Printed	Name	
Additional Trip	Required? Yes / No			
Description of \	Work:			
Customer Abus	e: Yes / No Explain			
Trip #	Date	On-Site At	Off-Site At	
Manager Signat	ture	Manager Printed	Name	
Additional Trip	Required? Yes / No			
Description of \	Work:			
Customer Abus	se: Yes / No Explain	:		
CHECKLIST		-2		
	is the length of the cable ru			
	•	ne cable for the placement of the Alt/E	attery tester?	
	the Manager on duty that o			
•	itional materials used that v			
	d time you worked with Eve	@AAP		
	t or INC # provided by Eve			
	is the issue with battery/alt			
	lays did you have if any? Pleimes, 1 hr looking for mate	ease provide times and delay descript	ions: Example: 30 mins due	



COMMENTS & SIGNATURES				
Manager Signature	Date & Time			
Tachairing Cianabasa	Date 9 Time			