

VENDOR W/O # 127361-01

Service Date 8/3/21 10:00 AM Client PO # Priority Regular Order Type Service SN Task # PRJTASK7240826

Telaid 13 West Main Street Niantic, CT 06357 Phone # 800-205-5556 Fax #

Contact Information Service Desk (866) 566-4295

SERVICE LOCATION AUTOZONE - Loc # 2741 - TUCSON, AZ 634 W. VALENCIA RD null TUCSON, AZ 85706 Phone # Fax # VENDOR # 380129 Intellicomm 1048 Chase Creek Ct Lawrenceville, GA 30044 Phone # 405-802-1262 Fax #

SERVICE DESCRIPTION Mac / Service

Ticket: 1950657

TECH MUST CHECK IN AND OUT WITH TELAID - CONTACT TELAID 866-566-4295 TO CHECK IN WHEN ARRIVING ONSITE

Tech is to call 901-495-6666, if no answer the tech should call 901-288-9288

Store Number: 2741 Ticket: 1950657

Cable run location: N/A Cable run device and/or Mac: N/A Network Biscuit ID: N/A Approx. Length of the cable: N/A Lift needed? No Problem description: Switch 2 needs to be replaced is damaged and for the store can be converted to SDWAN.

What troubleshooting steps that were taken to resolve the issue: Switch 2 is not reachable, called store and had them check cables.

Information needed for the tech: The new switch 2, power cord, and mounting brackets have been shipped to the store. The tech will need to get switch 2 installed and powered up, and will need to connect switch 1 and switch 2 using port 21.

CALL AUTOZONE AT 901-495-6666* TO TROUBLESHOOT *If no answer tech to call 901-288-9288

- CONTACT TELAID 866-566-4295 BEFORE LEAVING THE STORE.

Required Deliverables:

- Cable test result (pass/fail), if applicable.
- Pictures of new jack or equipment installed, if applicable.



VENDOR W/O # 127361-01

Service Date 8/3/21 10:00 AM Client PO # Priority Regular Order Type Service SN Task # PRJTASK7240826

Telaid 13 West Main Street Niantic, CT 06357 Phone # 800-205-5556 Fax #

Contact Information Service Desk (866) 566-4295

Doc Туре	Required Count	Description
After Photo	2	Before/ After Pictures of new jack or equipment installed, if applicable
Deliverable 1	1	AutoZone check out number provided by the AutoZone Service Team
Signature	1	Signoff

Telaid 13 West Main Street Niantic, CT 06357 Phone # 800-205-5556 Fax #	SIGN OFF SHEET VENDOR W/O # 127361-01	Service Date 8/3/21 10:00 AM Client PO # Priority Regular Order Type Service SN Task # PRJTASK7240826			
SERVICE LOCATION AUTOZONE - Loc # 2741 - TUCSON, AZ 634 W. VALENCIA RD null TUCSON, AZ 85706 Phone # Fax #		IVR Pin # 93244058			
SERVICE DESCRIPTION Mac / Service					
Ticket: 1950657					
TECH MUST CHECK IN AND OUT WITH TELAID - CONTACT TELAID 866-566-4295 TO CHECK IN WHEN ARRIVING ONSITE					
Tech is to call 901-495-6666, if no answer the tech should call 901-288-9288					
Store Number: 2741 Ticket: 1950657 Cable run location: N/A Cable run device and/or Mac: N/A Network Biscuit ID: N/A Approx. Length of the cable: N/A Lift needed? No Problem description: Switch 2 needs t	o be replaced is damaged and	d for the store can be converted to SDWAN.			
What troubleshooting steps that were taken to resolve the issue: Switch 2 is not reachable, called store and had them check cables.					
Information needed for the tech: The new switch 2, power cord, and mounting brackets have been shipped to the store. The tech will need to get switch 2 installed and powered up, and will need to connect switch 1 and switch 2 using port 21.					
CALL AUTOZONE AT 901-495-6666* *If no answer tech to call 901-288-92					
- CONTACT TELAID 866-566-4295 B	EFORE LEAVING THE STORE.				
Required Deliverables: • Cable test result (pass/fail), it • Pictures of new jack or equipr • Confirmation-of-any-work-per	ment installed, if applicable.	confirmed to-work-as required-by-AutoZone			
Print Date: 07/30/21 bmichael		Page 1 of 2			

Telaid 13 West Main Street Niantic, CT 06357 Phone # 800-205-5556 Fax #	SIGN OFF SHEET VENDOR W/O # 127361-01	Service Date 8/3/21 10:00 AM Client PO # Priority Regular Order Type Service SN Task # PRJTASK7240826
Store Manager's Signature		
Print Name	Date	
Time In	Time Out	